



Attention

Do not solder the connections between the pipes and valve body unless all internal parts are removed.